

31/2/13B

WATER WELL REPORT

STATE OF WASHINGTON

Start Card No. W 00366
Unique Well I.D. #
Water Right Permit No.

(1) OWNER: Name STONEMAN, JON Address 556 E COUGAR LANE CAMANO ISLAND, WA 98292-

(2) LOCATION OF WELL: County ISLAND - NW 1/4 NE 1/4 Sec 13 T 31 N., R 2 WM

(2a) STREET ADDRESS OF WELL (or nearest address) 226 S W CAMANO ISLAND, CAMANO ISLAND

(3) PROPOSED USE: MUNICIPAL (10) WELL LOG

(4) TYPE OF WORK: Owner's Number of well (If more than one) Method: ROTARY
NEW WELL

(5) DIMENSIONS: Diameter of well 6 inches
Drilled 417 ft. Depth of completed well 417 ft.

(6) CONSTRUCTION DETAILS: " Dia. from 0 ft. to 407 ft.
Casing installed: 6 " Dia. from ft. to ft.
WELDED " Dia. from ft. to ft.

Perforations: NO
Type of perforator used
SIZE of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

Screens: YES
Manufacturer's Name
Type STAINLESS STEEL Model No. TELESCOPING
Diam. 6 slot size 12 from 407 ft. to 417 ft.
Diam. slot size from ft. to ft.

Gravel packed: NO
Gravel placed from ft. to ft. Size of gravel

Surface seal: YES To what depth? 18 ft.
Material used in seal BENTONITE
Did any strata contain unusable water? NO
Type of water? Depth of strata ft.
Method of sealing strata off

(7) PUMP: Manufacturer's Name
Type H.P.

(8) WATER LEVELS: Land-surface elevation
Static level 358 ft. above mean sea level ... ft.
Artesian Pressure lbs. per square inch Date 11/08/93
Artesian water controlled by

(9) WELL TESTS: Drawdown is amount water level is lowered below static level.
Was a pump test made? If yes, by whom?
Yield: gal./min with ft. drawdown after hrs.

Recovery data
Time Water Level Time Water Level Time Water Level

Date of test / /
Bailer test gal/min. 48 ft. drawdown after hrs.
Air test 20 + gal/min. w/ stem set at ft. for 1 hrs.
Artesian flow g.p.m. Date
Temperature of water Was a chemical analysis made?

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change in formation.

MATERIAL	FROM	TO
DIRTY SAND & GRAVEL	0	30
BROWN CLAY	30	40
BLUE CLAY	40	75
BLUE CLAY & GRAVEL	75	95
BROWN CLAY & GRAVEL	95	146
SANDY BLUE CLAY	146	164
BROWN CLAY & GRAVEL	164	200
BLUE CLAY	200	235
BROWN CLAY	235	265
BROWN CLAY & GRAVEL	265	358
SAND	358	380
SAND & WATER	380	417

RECEIVED

NOV 16 1993

DEPT. OF ECOLOGY

Well Located According To
Island County Ordinance #809

Work started 11/03/93 Completed 11/08/93

WELL CONSTRUCTOR CERTIFICATION:
I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.

NAME DAHLMAN PUMP & WELL DRILL
(Person, firm, or corporation) (Type or print)

ADDRESS PO BOX 422, BURLINGTON, WA

[SIGNED] *Leo Becker* License No. 0623

Contractor's
Registration No. DAHLMWP123LC Date 11/09/93